G-IV-C-179

Shallmar Survey District Shallmar Multiple, private 1917- Present

The Shallmar Survey District includes a group of forty-five buildings within the town of Shallmar, a coal company town built between 1918 and the late 1920s on the North Branch of the Potomac River. These buildings stand on the western side of Shallmar Road which runs in a southwesterly direction between North Hill Road and Dodson. The district includes the structures originally built in Shallmar Road and Dodson. The district includes the structures originally built in Shallmar by the Wolf Den Mining Company (later the Shallmar Mine Company) to house its employees as well as the remains of buildings connected with the operation of the Wolf Den Mine. With only a few exceptions the houses face on both Shallmar Road.

The Shallmar Survey District is significant as an example of a company town in which houses were provided by the coal mining company for the exclusive use of its employees. Both in its conception and design Shallmar totally reflected the intentions of the parent company and its very existence therefore was inextricably linked to the fortunes of the Shallmar Mining Company.

## Maryland Historical Trust state Historic Sites Inventory Form

Survey No. 6-11-6-177

Magi No./2//365738

DOE \_\_yes \_\_no

1. Nam	findicate pr	eferred name)				
nistoric Sha	allmar Survey Distr	ict				
and/or common						
2. Loca	ation					
street & number				not for publication		
city, town	Shallmar	vicinity of	congressional district	Sixth		
state Mai	ryland	county	Garrett			
3. Clas	sification					
Category  _X district _ building(s) structure _ site _ object	Ownership public _X_ private both Public Acquisition in process being considered _X_ not_applicable	Status  X occupied  unoccupied  work in progress  Accessible X yes: restricted  yes: unrestricted  no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:		
4. Own	er of Prope	rty (give names a	nd mailing address	es of <u>all</u> owners)		
name	Multiple Owners	hip				
street & number			telephone no.:			
city, town		state	and zip code			
	ation of Leg	al Description	on			
		ett County Court Ho		liber		
street & number				folio		
city, town	Oakland		state	Maryland		
	resentation	in Existing	Historical Sur	veys		
™ie						
date			federal st	ate county loc		
depository for s	urvey records					
city, town			state			

Survey No.6-1V-C-179

Condition
\_\_\_\_ excellent
\_X good
\_X fair

X deteriorated ruins unexposed

Check one
\_\_\_\_ unaltered
\_X\_ altered

Check one
X.... original site
..... moved da

ed date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The Shallmar Survey District includes a group of forty-five buildings within the town of Shallmar, a coal company town built between 1918 and the late 1920s on the North Branch of the Potomac River. These buildings stand on the western side of Shallmar Road which runs in a southwesterly direction between North Hill Road and Dodson. The district includes the structures originally built in Shallmar by the Wolf Den Mining Company (later the Shallmar Mine Company) to house its employees as well as the remains of buildings connected with the operation of the Wolf Den Mine. With only a few exceptions the houses face on both Shallmar Road and the river, which runs parallel to the road and forms the town's eastern boundary. An abandoned stretch of the Wolf Den Branch of the Western Maryland Railroad running parallel to Shallmar Road forms the district's western boundary.

Although Shallmar was originally laid out with several short streets running perpendicular to Shallmar Road, few of the houses which once occupied sites on these sheets remain (Houses #5, 14, 15, 16, 21 and 26-29 on the accompanying map). Along Shallmar Road all of the buildings have a uniform setback of ten feet with the exception of house #12, a large house built for an official of the coal company, which has a more extensive front yard.

There are four distinct types of houses in Shallmar. Most typical is the two story, three bay wide frame house of stud construction with central door and front porch. Houses 6-11, 23-25, and 33-44 conform to this type, and the stretch of houses along Shallmar Road between 33-44 present a particulary uniform appearance.

Distinguishing characteristics of this type include the front porch supported by three turned posts, a cross gable set in the center of the long side of the gable roof, a jig sawn round ventilator in the middle of this cross gable (virtually the only decorative touch to these houses), a simple cornice above each window and door and a central chimney with corbelled cap House #35 retains an original front door with five raised horizontal panels.

Most of these houses have been enlarged with rear additions, varying in depth between one and four bays. Many, including #34, 36, 39, 41, 42 and 43 have an additional cinderblock chimney to one side of the house, although #44 has a second brick chimney which appears contemporary with the rest of the house. Otherwise, the majority of these houses present a generally uniform and unaltered appearance.

Houses #17-19 and #22 are all that remain of a considerable number of duplex houses which once stood in Shallmar. Each is two stories tall and four bays wide with German siding and a one story porch supported by turned posts. Two doors are placed close together in the middle of the gable end facade. A decorative ventilator similar to that which appears on other houses in Shallmar is placed in the center of the gable. Each side elevation has between eight and ten windows with two-over two sashes. The porch on #19 has an unusual slat balustrade, but otherwise these duplexes appear quite similar. Most have acquired various additions to the rear.

Houses 26-29 were built on a hill which rises near the point where Shallmar

8. \$	Significance	Survey No. 6-11-C-1	19
#riod pret 1400 1500 1600 1700 1800X 1900	0–1499 <u>X</u> archeology-historic 0–1599 <u>—</u> agriculture 0–1699 <u>X</u> architecture 0–1799 <u>A</u> art 0–1899 <u>X</u> commerce	— community planning       landscape architecture       relig         — conservation       law       scle         — economics       literature       scul         — education       military       soci         — engineering       muslc       hum         — exploration/settlement       philosophy       thea         X       industry       politics/government       X	nce pture
Specific	: dates	Builder/Architect	
check:		_B_C_D A_B_C_D_E_F_G nationalstatelocal	

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Shallmar Survey District is significant as an example of a company town in which houses were provided by the coal mining company for the exclusive use of its employees. Both in its conception and design Shallmar totally reflected the intentions of the parent company and its very existence therefore was inextricably linked to the fortunes of the Shallmar Mining Company.

The Wolf Den Mining Company (later renamed Shallmar Mining Co.) first began mining operations in this area in July of 1917. Two different but proximate mines in the Lower Kittaning Seam were worked and during its first year of operation a total of forty men produced 32,604 tons of coal. The mine proved to be unusually productive and employment figures jumped to fifty-six in 1919 and to one hundred and thirty by 1923.

By that time both the company and its town had been renamed Shallmar, after the company's president W. S. Marshall. The large increase in the company payroll during this period necessitated a parallel expansion in the number of new houses built in the community. A map of Shallmar prepared by the mining company in 1923 showed a total of ninety buildings in the town, an increase of almost forty houses in only four years.

Most other communities in Garrett and Allegany counties, although heavily dependent on the coal and rail industries for economic livelihood, were usually not as firmly tied to one particular company as was Shallmar. In this respect it shared many features of Kempton which, like Shallmar, sprang up almost overnight to serve the needs of its parent company. The establishment of a company town by a firm such as the Shallmar Mining Company was typical of the paternalistic attitude of much of corporate America in the 1920s and in many cases was undertaken to forestall the rise of militant unionism. Well-built and comfortable houses were "provided" to the miners, who were forced to lease their homes, with seldom an opportunity to buy them outright. The philosophy behind this attention paid to worker housing by the company was summed up by its superintendant, H. A. Marshall, who wrote that, "It (Shallmar Mine Company) might have clippeda few corners in the housing of its men, but from principle it has continuously given them considerate treatment, which pays in the long run."

10. Ge	ographical Data					
Acreage of nominated property  Quadrangle name UTM References do NOT complete UTM references			Quadrangle scale			
A Zone Easti		B Zone	Easting	Northing		
C		D				
Verbal bounda	ry description and justification					
List all states	and counties for properties overlap	ping state or c	ounty bound	laries		
state	code	county		code		
state	code	county		code		
11. For	m Prepared By					
name/title	Geoffrey Henry					
organization	Maryland Historical Trust		date Janı	uary 1983		
street & number	21 State Circle	t	telephone	,		
city or town	Annapolis		state	Maryland		

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

Road makes a slight bend. House #26 is the most typical of these houses and has undergone the least alteration. It is a one story, four bay frame building with a recessed porch and entry. At the rear of the three bay deep house is a small shed roofed porch. House #28 is raised on high foundations and has a side porch but is otherwise similar in appearance to both #26 and 27. House #29 is a modern non-contributing house.

Facing the athletic field are three houses (#14-16) of a type once quite numerous in Shallmar. Each is  $1\frac{1}{2}$  stories with a gable end entrance. A shed roof porch supported by turned posts extends along the front of the house, the one at #15 being recently enclosed. All three are three bays deep with a small porch at the rear. These houses are considerably smaller in scale than the single family houses along Shallmar road.

The house at #12, a late Queen Anne style building, is the largest in Shallmar, and was built to house the Superintendant. This large, two-and-one-half story, three bay wide frame house has an off-center front door reached by wide steps. The most outstanding feature of this house is the one story wrap-around porch which extends from the front part way around the north side of the house. A row of turned balusters runs between the square panelled Doric columns which support the porch. A hipped dormer with triple windows sits on both the north and east sides of the roof. Two large shed-garages stand twenty feet to the north of the house.

The different house types in Shallmar suggest a relationship between the size of a house and its occupant's position with the Shallmar Mining Company. Kempton, a coal mining town built by the Davis Coal & Coke Company during the 1910s on the Potomac River southwest of Shallmar bears many similarities to Shallmar. Along its main street were the houses of the company officials and skilled workers, all with front yards and cement sidewalks. The unskilled and foreign workders, on the other hand, lived in cheaper houses on roads with wooden sidewalks.

The sole commercial building in Shallmar is the former company store, now privately owned. It is a one-and-one-half story building constructed of local cut stone. Two entrances are provided on the front, one to the store proper, the other to the former pay office. The store entrance is framed by simple iron columns and all of the windows have iron bars. Above each of the windows and doors is a transom; those above the two widest windows are divided into four panes. A heavy wooden cornice, runs along the top of the transoms. It is painted green with the words "Vera's Market" painted white. Only a few letters of the words "Shallmar Coal Co." are still visible.

Above the cornice is the date 1920 in raised numerals. A slightly projecting ledge of stone serves as a cornice for the facade.


The side elevations are three bays deep, with each bay slightly smaller than the one preceding it, and are windowless.


Much of the interior is intact including floor-to-ceiling wooden shelves on both side walls, a carved wooden cornice running the length of the building and a well-preserved pressed tin ceiling. In the rear is a vault, once used for storing ice. Separate space was also provided for a post office and a pay office.

Very little physical evidence of mining operations by the Shallmar Mining Company remain in this area. In addition to the mine openings these included a power generating house, saw mill, offices, tipples, smith shops and several watchmen's posts. The power house was particularly noteworthy and was built of cut stone, with large thermal windows on both the facade and eastern elevation.

Fortunately for Shallmar, the high output which the coal mine maintained during the 1920s and 1930s ensured an uninterruped level of prosperity for the community. Old photographs from this period show a neat and well cared for village, with picket fences, arbors and neat cairns of whitewashed stones piled in front of the driveways. The town was provided with a school, athletic field and store, as well as a post-office.

The coal tonnage began to decline in the 1930s and by 1959, the BB&U Coal Company, successor to Shallmar, mined only 9,236 tons with twelve employees. Most of the buildings connected with the mining operations were later destroyed as was the school. The houses were sold off and often destroyed by their later owners, so that only thirty-seven of the original houses built in the 1920s still stand. Those that remain are for the most part less carefully maintained than they were during Shallmar's hey-day.





URS Greiner Woodward Clyde Federal Services Engineering & sciences applied to the earth and its environment


CLIENT: FEMA HMGP LOCATION: Shallmar Historic District, Maryland (<u>Survey# G-IV-C-179</u>)


PROJECT No. DATE: 10/25/99 CHK'D. C.L.A. 89FR954349

SCALE: 1/8" = 1'-0"

Second Floor Plan 1062 Shallmar Road

FIGURE: 2







URS Greiner Woodward Clyde Federal Services
Engineering & sciences applied to the earth and its environment


CLIENT: FEMA HMGP LOCATION: Shallmar Historic District, Maryland (Survey# G-IV-C-179)

PROJECT No. DATE: 10/25/99 CHK'D. C.L.A. 89FR954349

Second Floor Plan 1108 Shallmar Road

FIGURE: 2

SCALE: 1/8" = 1'-0"




URS Greiner Woodward Clyde Federal Services Engineering & sciences applied to the earth and its environment

CLIENT: FEMA HMGP LOCATION: Shallmar Historic District, Maryland (Survey# G—IV—C—179)

PROJECT No. DATE: 10/25/99 CHK'D. C.L.A. 89FR954349 SCALE: 1/8" = 1'-0"

First Floor Plan 1116 Shallmar Road

FIGURE: 1





URS Greiner Woodward Clyde Federal Services Engineering & sciences applied to the earth and its environment

CLIENT: FEMA HMGP LOCATION: Shallmar Historic District, Maryland (Survey# G-IV-C-179)


PROJECT No. 89FR954349


DATE: 10/25/99 CHK'D. C.L.A.

Second Floor Plan 1116 Shallmar Road

FIGURE: 2

SCALE: 1/8" = 1'-0"







## URS Greiner Woodward Clyde Federal Services Engineering & sciences applied to the earth and its environment

CLIENT: FEMA HMGP LOCATION: Shallmar Histaric District, Maryland (Survey# G-IV-C-179)


PROJECT No. 89FR954349

DATE: 10/25/99 CHK'D. C.L.A.

Second Floor Plan 1118 Shallmar Road


FIGURE: 2

SCALE: 1/8" = 1'-0"



PROJECT No. B9FR954349 DATE: 10/25/99 CHK'D. C.L.A. First Floor Plan 24 Ballfield Lane FIGURE: 1

SCALE: 1/8" = 1'-0"





CLIENT: FEMA HMGP LOCATION: Shallmar Historic District, Maryland (Survey# G-IV-C-179)


PROJECT No. 89FR954349

DATE: 10/25/99 CHK'D. C.L.A.

First Floor Plan 42 Ballfield Lane

FIGURE: 1

SCALE: 1/8" = 1'-0"





CONTOUR INTERVAL 20 FEET NATIONAL GEODETIC VERTICAL DATUM OF 1929

PORTH

THIS MAP COMPLIES WITH NATIONAL MAP ACCURACY STANDARDS FOR SALE BY U.S. GEOLOGICAL SURVEY, RESTON, VIRGINIA 22092 A FOLDER DESCRIBING TOPOGRAPHIC MAPS AND SYMBOLS IS AVAILABLE ON REQUEST QUADRANG



## G-IV-C-179

Shallmar Survey District Garrett County, Maryland Shallmar Road North from house #2 G. Henry 1/83



G-/V-C-/79


G-V-C-177

Shallmar Survey District
Garrett County, Maryland
Shallmar Road
North From House #37
G. Henry 1/83



G-1V-C-179 G-V-C-177

Shallmar Survey District Garrett County, Maryland Shallmar Road North from house #33 G. Henry 1/83



G-1V-C-179

Shallmar Survey District Garrett County, Maryland Shallmar Road looking north from #34 G. Henry 1/83



## G-|V-C-|79 G-V-C-177 Shallmar Survey District Garrett County, Maryland House #18 East elevation G. Henry 1/83



G-IV-C-179
G-V-C-177
Shallmar Survey District
Garrett County, Maryland
House #9

East facade G. Henry 1/83



G-IV-C-179 -G-V-C-177 Shallmar Survey District Garrett County, Maryland House #18

NE Corner G. Henry 1/83



G-1V-C-179 G-V-C-177

Shallmar Survey District Garrett County, Maryland House #35 East facade G. Henry 1/83



G-1V-C-179 G-V-C-177

Shallmar Survey District Garrett County, Maryland Houses #16, 15, 14 looking west G. Henry 1/83



### G-1V-C-179 G-V-C-177

Shallmar Survey District Garrett County, Maryland Houses #17, 18, 19 looking NW G. Henry 1/83



#### G-/V-C-/79 G-V-C-177 Shallmar Survey

Shallmar Survey District Garrett County, Maryland House #12 Oblique NE view

G. Henry 1/83



## G-1V-C-179 -G-V-C-177

Shallmar Survey District Garrett County, Maryland House #12 North elevation

G. Henry 1/83



#### G-IV-C-179 -G-V-C-177

Shallmar Survey District Garrett County, Maryland House #45 Oblique view G. Henry 1/83




G-/V-C-179 G-V-C-177 Shallmar Survey District Garrett County, Maryland House #45 East facade G. Henry 1/83



## G-1V-C-179 -G-V-C-177

Shallmar Survey District Garrett County, Maryland View of mountain west of Shallmar G. Henry 1/83



Shallmar Survey District Garrett County, Maryland Building #13 NE corner

G. Henry 1/83



## G-1 V-C-179 -G-V-C-177

Shallmar Survey District Garrett County, Maryland House #26 East facade G. Henry 1/83



# G-/V-C-/79 G-V-C-177 Shallmar Survey Dis

Shallmar Survey District Garrett County, Maryland House #17 South facade G. Henry 1/83